

Eight Tips to Extend Your Medfusion 3010a Pump's Life



888-509-8760 www.aiv-inc.com aivsales@aiv-inc.com



Infusion pumps are an essential part of hospitals, physician offices, outpatient surgery centers, emergency service vehicles and veterinary clinics. But what happens when they break down or just stop performing in peak condition after years of wear and tear?

Despite new models coming out each year from various manufacturers, your Medfusion 3010a Infusion Pumps were built to provide years of safe and efficient operation. Here are AIV's top tips for extending the life of your Medfusion 3010a Infusion Pump:

Tip 1: Replace the Batteries Regularly

Sometimes, pump failure could simply be due to old batteries in your unit. The rechargeable batteries found in your Medfusion 3010a hold a charge less effectively over time. Regular replacement of these batteries will lessen the chances of false error codes and inadvertent pump shutdown.

Second-source medical battery suppliers can also be just as effective as the old OEM battery, provided that the replacement battery is rated and constructed for use in specific IV pump models.

Tip 2: Replace the Infusion Pump Casing and Exterior

Replacing the exterior parts of the Medfusion 3010a not only protects against fluid invasion and other issues, it also visually presents the pump positively to the patients it is used on. These cases are available from AIV; brand new top case assemblies (AIV Part #: MD13274) for the Medfusion 3010a on their website.

Tip 3: Repair/Restore Broken Pumps

A malfunctioning pump does not necessarily mean it must be discarded. Many failures happen that can be easily accessed and replaced, significantly lowering the department's overhead costs. There are many repair options available:

a. Diagnose and Repair In-House

Before anything else, try consulting your in-house professionals. You not only save time but money as well when you reach out to your resident technician versus outsourcing advice from a third-party service.

888-509-8760 aivsales@aiv-inc.com | 2



b. Outsource Repairs and/or Services to A Third Party

Alternatively, you can also have your Medfusion 3010a pump serviced by a third-party vendor like AIV that you trust and maintain a strong relationship with. AlV's technicians and staff can be very helpful with emergency repairs and other services. AIV provides a 120-day warranty on all new replacement parts, and pump repairs with a 6-month warranty. For the full list of additional Medfusion 3010a repair services that AIV currently offers, click here.

All AIV repairs are performed in their ISO 13485:2016 certified facilityISO-13485 registered facility to strict quality standards. They offer both flat rate, all-inclusive pump repairs (AIV Service #: FLRTMED3010a) as well as fixed-rate labor (AIV Service #: RPMED3010a) repairs to suit your budgeting needs.

Tip 4: Attend to Warnings and Nuisance Alarms Promptly

Attending to pump warnings and alarms immediately will keep your infusion device well-calibrated and in good working condition. The most common parts that may require recalibration or replacement often include the case and keypad.

If you find that your Medfusion 3010a needs to have its parts replaced, you can look into either purchasing used parts or new parts. Used parts are a more cost-effective option between the two. Keep in mind that for older pumps, this may be the only option. Make sure that any used parts you buy are tested and certified by the reseller to ensure proper function.

Most internal components of an infusion pump can be replaced, giving you a budget-friendlier alternative to purchasing brand new equipment. AIV supplies new parts for the Medfusion 3010a, both of which include a warranty, 120-days for new replacement parts and a 60-day warranty on recertified parts.

Tip 5: Perform Regular Service (PMs)

Regular pump service can proactively identify and mediate issues that may cause the pump to malfunction. Medfusion preventive maintenance covers inspection for physical damage, battery level, and power cords. It also includes calibrations procedures.



Tip 6: Maintain and Clean Power Cords

Not only can faulty wiring cause damage to the pump itself, but it can also make it unsafe for clinical staff and patients to use. Ensure all electrical cords are clean and damage-free through regular cleaning and maintenance. Early detection of cable issues may enable the repair instead of replacement of the part. Once faults are discovered however, be sure to replace them immediately. New power cords can easily be purchased from providers like AIV.

Tip 7: Undertake Additional Infusion Pump Training

Regular education on pump function and common problems will enable your facility to diagnose and correct common pump problems. Many biomedical conferences, such as the CMIA or AAMI annual conferences, offer these seminars free of charge to biomedical professionals.

Tip 8: Purchasing Additional Models of Equipment Required

Purchasing several models of the same pump can be a good insurance policy for your institution. Quantity discounts are available from some distributors, and the extra pumps can be used as substitute floor units, or for replacement parts.

Replacing your current machines with all-new equipment doesn't have to be the only solution! By following these top eight tips, you can add several more years of safe usage to your Medfusion 3010a infusion pump devices and earn additional savings for your facility.

For reliable, quality-driven Medfusion 3010a infusion pump replacement parts and services, call on AIV. AIV manufactures keypads and cases to strict quality standards in our US based ISO 13485:2016 certified facility. In addition, all Medfusion 3010a pump maintenance and repairs are performed by AIV's trained and experienced technicians. This Is why AIV's Medfusion 3010a pump replacement parts and Medfusion 3010a infusion pump repairs are trusted by hospitals worldwide.



Need more help with your Medfusion 3010a infusion pump? Contact AIV today at **888-509-8760** or send an email to <u>aivsales@aiv-inc.com</u>.

888-509-8760 WWW.aiv-inc.com aivsales@aiv-inc.com

7485 Shipley Avenue Harmans, MD 21077